

EQUIPMENT FAILURE AND CORROSION CONTROL PROGRAM

Ralph J. Harding III - Jerry L. Tabb
Texaco USA

ABSTRACT

This paper discusses the methods currently used by Texaco's Midland Producing Division to monitor and reduce equipment failures and chemical usage. The cost effectiveness of the program is readily apparent having resulted in a 50+ percent reduction in the failure and maintenance cost from the first quarter 1986 to the second quarter 1989.

The items presented in the paper include the methods of reporting, tracking, and reviewing equipment failures and chemical usage. Included in the presentation are examples of surface and subsurface failure reporting forms, equipment failure data base, chemical selection and testing criteria outline, monthly chemical reporting format, quarterly meeting format, and report of special equipment being tested.

INTRODUCTION

During the late 1980's, various groups within the company had successfully utilized a prototype Equipment Failure System (EFS) mainframe program and quarterly meetings to monitor downhole failures. It became readily apparent that use of such a system could result in an improvement throughout the Division. Over the past four years the EFS program and quarterly meetings have been improved and expanded to all the Areas in the Midland Producing Division, resulting in a 50+ percent reduction in downhole failure rates and failure costs from the first quarter 1986 to the second quarter 1989.

The goals of the Equipment Failure Program were threefold: (1) to reduce failures and failure expense, (2) to optimize maintenance repair expense, and (3) to assist in evaluating the chemical program. These goals were accomplished by accurate identification of failure cause, monitoring with the EFS Computer Program and through Quarterly Meetings in the respective Areas.

DISCUSSION

The Equipment Failure System data base is separated into two parts, surface failures and sub-surface failures. Although the sub-surface portion is used by all the Area offices in the Midland Producing Division, the surface failure portion is used only by a few Areas at this time. For purposes of this paper we are going to concentrate mainly on the sub-surface portion.

ACQUISITION AND STORAGE OF FAILURE DATA

The first step in an effective failure control program is the accurate identification of the failure. This is the single most important factor in correcting the problem. In the past many failures were attributed to improper or insufficient chemical treatment when in fact the real problem was a mechanical problem that no amount of additional chemical would eliminate. An example would be corrosion pitting along a rod wear line. This type of failure was often attributed to corrosion and the chemical treatment volume or frequency was increased accordingly. Adding sinker bars, slowing the unit down, or installing a smaller pump are better alternative corrective actions. The corrosion probably would not have occurred if the rod had not scored the tubing, wearing off the inhibitor film.

To assure proper cause identification, many Areas require the Foreman, Engineer, and Chemical Company representative to all examine the failure. If the cause and corrective action is not readily apparent, a piece of the failed equipment is sent to the Texaco Research Lab in Houston for analysis. In addition to requiring all parties to visually inspect the failure, emphasis was placed on correcting the problem before hanging the well back on even if this resulted in one or two days downtime. Foremen also maintain a list of recommended changes to equipment and operating parameters which will be implemented after the next failure for wells that are historically "problem" wells. When a well on the list fails, the Foreman checks with all parties involved to be sure the recommendation for corrective action is still valid.

Once the failure and cause have been identified, the Foreman completes a Sub-Surface or Surface Equipment Failure form (Tables 1 and 1A). Input data for the form includes the lease name, well number, date, depth of failure, failing equipment, well type, location of failure, code for pulling unit and crew, optional comments, and costs including labor, equipment, and maintenance. The forms are sent into the office for review by the Area Corrosion Technician and Field Engineer prior to input into the Equipment Failure System data base.

Data in the EFS data base can be retrieved in a variety of different report formats, both detail lists and summary type. The reports can also be pulled by Division, Area, Sub-Area, lease, or individual well. The most essential reports are the Problem Well Report (Table 2) and Repeat Failure Report (Table 3). The problem well report actually allows the user to define a problem well. Texaco defines a problem well as one that has two or more failures of the same equipment type or four failures of any

type in the last 12 months with at least one of those failures occurring in the current quarter. A repeat failure is defined as two or more failures of the same equipment type occurring within six months, with at least one of them occurring in the current quarter. Wells that appear on these reports are carefully analyzed and evaluated to determine the most cost effective action to reduce the failures and associated costs on these wells.

Another report that is useful lists failures by equipment type, location, and cause (Table 4). With this report contractor performance can also be evaluated. For example, all improper makeup (IMU) failures can be reviewed for a given time period to determine if the make-up procedure of a particular pulling unit crew may be responsible for excessive IMU failures. If this happens, the crew will be reminded of Texaco's recommended rod handling procedures. If the problem is not corrected, their services may be terminated.

In addition to the above, the computer also aids in tracking the performance of particular equipment being tested. By using the comment section, the metallurgy or manufacturer of specific test items can be indicated and compared with other products currently being used (Table 5).

REVIEW OF FAILURE DATA

The information stored in the data base is used to generate reports and graphs for the quarterly meetings on both Area and Sub-Area basis (Tables 6 through 13). Most of the meetings are attended by the Division Corrosion Engineer, Area Manager, Senior Engineer, Production Supervisors and Foremen, Field Engineers, and Field Technicians. The cross-section of personnel that attend the meetings help disseminate information, technology, and techniques between Area offices and provide a forum to discuss the benefits and concerns (regarding solutions to problems) by drawing on the experience and knowledge of other personnel in the Area. The purpose of most of the graphs and tables in the report is for historical comparison and thus serves as an indicator of progress compared to previous quarters.

Much of the emphasis in the meetings focuses on the Problem Wells. The Problem Well Sheet (Table 14) concentrates attention on wells which have an extraordinary number of failures and expenses. Prior to the meeting a Field Technician is sent to each of the problem wells to gather operating data, shoot fluid levels, and run dynamometer cards. During the meeting the data is reviewed and a plan of action is formulated. This action may be an immediate change or one to be performed at the next failure. Examples of immediate action are slowing the unit down, lengthening the stroke, increasing inhibitor or treatment frequency, etc. Examples of action to be taken at the next failure are: reduce the pump size, install a charger valve, install fiberglass rods, etc.

Other ideas and suggestions which arise from the meeting must be further evaluated before implementing. This requires a cooperative "team effort" between Foremen and Engineers.

The effectiveness of the chemical treating program can also be seen at the quarterly meetings. Where the cause of failures on a particular lease or group of leases is described as corrosion, the chemical program is reviewed by the Foreman and Engineer. Together they can determine whether there is insufficient inhibitor being used, if the treating method is incorrect, if wells are being skipped by the vendor, etc. Naturally, leases being over treated will not be identified by this method.

The meetings also help evaluate the need for training of both Texaco personnel and vendor personnel. Several seminars have resulted from suggestions made in the quarterly failure meetings. Some of the seminar topics included downhole pump schools, paraffin treating schools, tubular and vessel coating seminars, dynamometer card interpretation schools, etc. Pulling unit crews have attended rod and tubing handling seminars.

CHEMICAL TREATMENTS

Chemical treatment must be justified before a program is established. The Midland Producing Division does not encourage chemical treatment for "insurance" purposes. Before a treatment program is established, vendors must first run chemical screening tests as outlined in Company guidelines (Table 15). These requirements help assure that the most cost effective chemical is selected, whether it is a corrosion or scale inhibitor, demulsifier, paraffin solvent, biocide, etc. When obtaining a proposal several vendors are solicited for treating recommendations. The one which is considered most cost effective (quality of service and technical competence included) is then selected for the job. NOTE: The lowest cost chemical proposed is not necessarily the one selected.

REVIEW OF CHEMICAL USAGE

Closely related to the failure program is the Chemical Usage Report that is provided monthly by the vendors. This PC-generated report, required from the vendors by Texaco, allows a quick well-by-well look at the chemical treating program (Table 16). Some of the specific information provided on the report is treatment volume, treatment frequency, flush volume, target and actual ppm rates, coupon data, and date of last failure including whether the failure is corrosion related or not. In most cases an entire lease can be reviewed in a couple of minutes to determine if all treatments are within the set limits. A little additional time spent reviewing the form can identify areas where a reduction in chemical usage may be possible and specific wells may be selected to test the feasibility of reducing treatments. Another valuable aspect of the monthly chemical usage report is that it forces the vendor to optimize his recommended program and keeps him more abreast of production changes.

One Area office in the Midland Producing Division currently holds Quarterly Chemical Usage Meetings which are attended by the Division Corrosion Engineer, Area Manager, Senior Engineer, Production Supervisors and Foremen, Field Engineers, and the respective chemical company representative. In these meetings the chemical treating

program on each lease and well is reviewed. The review includes items such as bacteria, oxygen, scale, corrosion, paraffin, emulsions, and surface treating. In several fields the use of chemicals has been totally eliminated as a result of these reviews and subsequent testing. In other locations more effective chemicals or application methods have been found.

REPORT OF SPECIAL EQUIPMENT BEING TESTED

Once each quarter Engineers update a list of non-routine equipment being tested in their Area (Table 17). Examples of items considered reportable are: specific name brands of roller rod guides, special couplings, sand screens, charger valves, coatings, etc. The reports are compiled at the Division level and disseminated back to each Area. In this manner each Area benefits from the experience of the others without spending time and money "re-inventing the wheel."

FUTURE PLANS

Work is currently in progress on a PC version of the EFS data base which will have much more versatility than the existing mainframe version. The PC version will be able to access other data bases, such as production, well status, etc., and generate reports and graphs in a format for presentation at the quarterly meetings. This will result in a significant manpower savings in preparing the quarterly reports.

With the elimination of most of the "repeat failures" and "problem wells," more engineering time will be devoted to the design and metallurgy of specific equipment in order to achieve the most cost effective run times and to reduce power consumption.

Based on the success of the quarterly chemical meeting in the one Area, other Areas in the Division plan to start conducting similar meetings.

SUMMARY

Through the use of a computer data base, team effort, and structured operational procedures, the failure rates and associated costs have been reduced over 50 percent from the first quarter of 1986 through the second quarter of 1989. The Division-wide failure rate is approximately 0.70 failures per pumping well per year and the trend is still downward.

SUB-SURFACE EQUIPMENT
FAILURE AND MAINTENANCE REPORT

LEASE OR PROPERTY NAME

PENWELL UNIT

TITLE NO.		WELL NO.		RESERVOIR CODE		DATE		
9 6 2 5 4 3 0 7		1 3 5 7				MONTH	DAY	YEAR
						0	4	0 1 8 9
FAILURE	ROD Sucker Rod	FG Flowing Gas	BDY Body	CF Corrosion Fatigue	DEPTH OF FAILURE			
	POR Polish Rod	FO Flowing Oil	UPS Upset	INT Internal Corrosion				
	HSR Hollow Sucker Rod	GL Gas Lift	PIN Pin	EXT External Corrosion		3732		
	TBG Tubing	PO Pumping Oil	CLP Coupling	EMB Embrittlement		COST OF FAILURE		
	GLV Gas Lift Valve	GI Gas Injection	BRL Barrel	TYD Tensile Yield		LABOR & EQUIPMENT		
	PMP Pump, Rod	WI Water Injection	PLG Plunger	WEW Wear		1944		
	HPM Hydraulic Pump	WS Water Source	PT Pull Tube or Rod	UNS Unscrewed		MATERIALS		
	SPM Subm. Cent. Pump	WD Water Disposal	VLC Valve Cage	IMU Improper Make-up				
	PKR Packer	PG Pumping Gas	BS Ball & Seat	ELE Electrical				
	REG Regulator		MND Mandrel	SCL Scale				
ANC Anchor		PMP Pump (Subm.)	SND Sand					
CSG Casing		MTR Motor (Subm.)	MUD Mud					
RDG Sucker Rod Guide		PRT Protector (Subm.)	PAR Paraffin					
RMD Remedial		CBL Cable (Subm.)	SLT Salt					
WR Well Record		OTH Other (w/Remarks)	OTH Other (w/Remarks)	109				
PREVENTIVE	ROD Sucker Rod	SPM Subm. Cent. Pump	RMN Routine Mainten.	UPG Upgrade	COST			
	POR Polish Rod	PKR Packer	VIN Visual Inspec.	HYT Hydraulic Test		LABOR & EQUIPMENT		
	HSR Hollow Sucker Rod	REG Regulator	EIN Electronic Inspec.	STM Steam		150		
	TBG Tubing	ANC Anchor	CPA Cut Paraffin	OTH Other (w/Remarks)		MATERIALS		
	GLV Gas Lift Valve	CSG Casing				2257		
	PMP Pump, Rod	RDG Sucker Rod Guide				COST		
	HPM Hydraulic Pump	OTH Other				LABOR & EQUIPMENT		
						150		
						MATERIALS		
						500		
MAINTENANCE	ROD Sucker Rod	SPM Subm. Cent. Pump	RMN Routine Mainten.	UPG Upgrade	COST			
	POR Polish Rod	PKR Packer	VIN Visual Inspec.	HYT Hydraulic Test		LABOR & EQUIPMENT		
	HSR Hollow Sucker Rod	REG Regulator	EIN Electronic Inspec.	STM Steam		35		
	TBG Tubing	ANC Anchor	CPA Cut Paraffin	OTH Other (w/Remarks)		MATERIALS		
	GLV Gas Lift Valve	CSG Casing				1300		
	PMP Pump, Rod	RDG Sucker Rod Guide						
	HPM Hydraulic Pump	OTH Other						
REMARKS	Tested tubing. Split 4 jts above SN. Added 9 roller rod guides.					SIGNED:		
	Add 4-1 1/2" K bars. Replaced 40 - 7/8" cplg.						Mark Made	
					P.U. CODE: KU-3			

TABLE 1

SURFACE EQUIPMENT FAILURE AND MAINTENANCE REPORT

LEASE OR PROPERTY NAME

PENWELL UNIT


TITLE NO.										WELL NO.										GROUP										DATE			
9	6	2	5	4	3	0	7									T	B									0	7	2	1	8	9		
EQUIPMENT										SERVICE										LOCATION										CAUSE			
FLN Flowline, Injec. Line SEP Separator HTT Heater-Treater KNO Knock-Out LHN Line Heater <u>TNK</u> Tank CHK Choke VAL Valve (Rmks) MET Meter PIP Piping (Facil., Pits.) FIL Filter DBD Dry-Bed Dehydrator ABS Absorber CNT Contactor FRC Fractionator STB Stabilizer STL Still EXC Exchanger (Rmks) BLR Boiler RBL Re-Boiler RGN Regenerator FRH Fired Heater ACM Accumulator FLT Flash Tank SRT Surge Tank CNI Control Instrument TRB Turbine ENG Engine (Rmks) EMO Electric Motor PMP Pump (Rmks) CMP Compressor GEN Generator PMU Pumping Unit BOT Boat OTH Other (Rmks) WLH Wellhead										OIL Oil GAS Gas <u>CND</u> Condensate <u>WTR</u> Water AIR Air PHY Process Hydrocarb. (Rmks) CHM Chemical (Rmks) GLY Glycol (Rmks) AMN Amine (Rmks) ABO Absorption Oil (Rmks) HTO Heating Oil STM Steam RFG Refrigerant (Rmks) TRT Treating SET Settling DST Desalting A/P Air/Process W/P Water/Process S/P Steam/Process O/P Heating Oil/Process P/P Process/Process WTI Water Injection GSI Gas Injection ARI Air Injection LSF Lease Facilities ELP Electric Power PRC Process Control (Rmks) PMD Pump Drive CMD Compressor Drive GND Generator Drive PUD Pumping Unit Drive BTD Boat Drive OTH Other (Rmks)										BDV Body THD Thread CPL Coupling WLD Weld NZL Nozzle TBE Tube TRY Tray BWH Bolt/Weld/Hardware <u>SHL</u> Shell MOD Mud Drum SMD Stead Drum GSS Gas Section OCS Oil/Condensate Section WTS Water Section HED Head CRH Cross-Head PSR Piston Rod RDP Rod Packing PST Piston PIR Piston Rings CYL Cylinder/Liners VAV Valves (Rmks) BLT Belts SHF Shaft PRT Port SPP Spark Plugs WTP Water Pump RAD Radiator BRG Bearing SMT Starting Motor CLH Clutch MAG Magneto ELS Electrical Sys. CLS Cooling Sys. HYS Hydraulic Sys. LBS Lubricating Sys. FIL Filter (Rmks) TRC Turbocharger IMP Impeller GRB Gear Box HDH Hull/Deck/Housing OTH Other										<u>INT</u> Internal Corrosion EXT External Corrosion ECL Excessive Loading ECP Excessive Pressure ECH Excessive Heat EMB Embrittlement BLS Blistering ILB Improper/No Lub. IAP Improper Applic. WER Wear ABR Abrasion SND Sand SCL Scale MUD Mud PAR Paraffin CAR Carbon OTH Other			
																														COST			
																														Outside Service			
																														1800			
																														Company Labor & Equip.			
																														300			
																														Materials			
																														1000			
TYPE EXPENSE																																	
<u>FLR</u> Failure MNT Maintenance MJO Major Overhaul																																	
REMARKS																				SIGNED													
Tank & Internal Coating 9 years old. Coating is beginning to peel off. Blasted and recoated tank.																																	

TABLE 1A

DATE RUN 01/03/90

SUB-SURFACE EQUIPMENT FAILURE PROBLEM WELL DETAIL LISTING
REPORT NO 969012

PAGE 9

DISTRICT 2 MIDLAND					AREA 1 ODESSA				SUBAREA2 PENWELL				
PROPERTY NUMBER 96254307					PROPERTY NAME: PENWELL UNIT					RESERVOIR CODE:		WELL NUMBER 1357 00	
DATE	FAILURE DATA EQP SVC LOC CSE DEPTH				MAINT EQP TYP	COST LAB-EQP	COSTS MATRLS	TOTAL COST	REMARKS				
7/07/88	PMP	PO	PLG	WER	3800		480	247	727	CHANGED PUMP. RINGS ON PLUNGER WERE WORN OUT. KU-3			
11/17/88	TBG	PO	BDY	INT	3820		2460	140	2600	TBG LEAK. TAG BTM. SHEARED TAC. CO 20' OF SAND W/HYD BLR. REPL TAC & PMP. KU-3			
					OTH RMN		550		550				
					ANC RMN		35	392	427				
					PMP RMN		35	443	478				
12/02/88	POR	PO	BDY	OTH	16		464	120	584	CLEAN SMOOTH BREAK W/NO SIGNS OF SEVERE CORROSION. SENT SAMPLE FOR ANALYSIS. KU-846			
2/25/89	PMP	PO	BRL	WER	3820		702	2600	3302	INST 2 S/O RDG/ROD. CHG 12 1" CLP,HVY WALL BRASS PUMP BRL COLLPSD (WEAR) PLG CORROSION, KU-3			
					RDG UPG			1955	1955				
					ROD RMN			137	137				
4/01/89	TBG	PO	BDY	WER	3732		1944	109	2053	TST TBG. SPLIT 4JASN. INST 9 ADD'L RLR RDG,4 ADD'L 1-1/2 KBARS. REP 40 7/8 CPLS, PMP & ANC. KU-3			
					RDG UPG		150	2257	2407				
					ROD RMN		150	500	650				
					PMP RMN		35	1300	1335				
					ANC RMN		100	570	670				
5/16/89	TBG	PO	OTH	OTH	3600		1945	109	2054	TSTD TBG W/PMP TRK-LEAKED. EST. FAIL. @3600. RAN NEW STRNG OF 2-7/8 TBG. CHG PMP & TAC. KU-3			
					TBG UPG		400	12768	13168				
					ANC RMN		35	59	94				
					PMP RMN			2800	2800				

									35991				

YEAR ENDING: 6/30/89

WELLS WITH FAILURES EQUAL TO OR GREATER THAN:
2 - ROD; OR 2 - TBG; OR 2 - PMP; OR 2 - HPM; OR 2 - SPM; OR 4 - TOTAL

TABLE 2

PAGE 1

90-01-03 14:56:12

SUBSURFACE FAILURE FILE

FROM 040189 TO 063089
 DIVISION: 6 MIDLAND
 DISTRICT: 2 MIDLAND

AREA: 1 ODESSA
 SUBAREA: 2 PENWELL

WELL	DATE	FAILURE EQU SVC	LOC CSE	DEPTH	MAINT EQP TYP	COST LABOR EQUIP	COST MATRLS	TOTAL COST	CONTROL	REMARKS
PROPERTY: 96254125 ECTOR FEE UNIT 11 RESERVOIR CODE:										
9	042489	TBG PO	CLP WER	12000		3206	236	3442		2JT OF 1-1/4 10RD IJ SPLIT IN CPL AREA DUE TO WEAR FROM RUNNING TBG. KU-3
9	051389	TBG PO	CLP WER	12000	HPM RMN	2972	118	3090		19 DS TBG UPS & PINS (SEV WER-COULD NOT MAKE UP) NEW STRG 1-1/4" TBG. REPL PMP. KU-3
					TBG UPG	700	46238	46938		
					HPM RMN		986	986		
PROPERTY: 96254307 PENWELL UNIT RESERVOIR CODE:										
1357	040189	TBG PO	BDY WER	3732		1944	109	2053		TST TBG. SPLIT 4JASN. INST 9 ADD'L RLR RDG. 4 ADD'L 1-1/2 KBARS. REP 40 7/8 CPLS, PMP & ANC. KU-3
					RDG UPG	150	2257	2407		
					ROD RMN	150	500	650		
					PMP RMN	35	1300	1335		
					ANC RMN	100	570	670		
1357	051689	TBG PO	OTH OTH	3600		1945	109	2054		45 DS TSTD TBG W/PMP TRK-LEAKED. EST. FAIL. @3600. RAN NEW STRNG OF 2-7/8 TBG. CHG PMP & TAC. KU-3
					TBG UPG	400	12768	13168		
					ANC RMN	35	59	94		
					PMP RMN		2800	2800		
2314	042189	TBG PO	BDY WER	3555		2490	981	3471		TBG SPLIT 9 JASN. ROD WEAR. BUSTED 8JT TSTG. RAN 4 ADD'L KBARS & 8 ADD'L RLR RDG. REP. PMP. KU-14
					ANC RMN	35	570	605		
					ROD UPG		692	692		
					RDG UPG		1466	1466		
					PMP RMN	35	1265	1300		
2314	061889	TBG PO	BDY WER	3447		1524	115	1639		58 DS REPL TBG STRG. RAN 4 ADD'L KBARS & 8 ADD'L RLR RDG. KU-14
					TBG RMN	300	13594	13894		
					RDG UPG		1498	1498		
					PMP RMN	35	63	98		
					ROD UPG		692	692		
4248	042189	PMP PO	BS WER	4264		510	41	551		CHANGED PUMP. KU-6
4248	050689	PMP PO	OTH OTH	4278		924	41	965		15 DS PUMP CHANGE. INSTALLED 6 - 1-1/2" K-BARS. NO REASON FOR FAILURE. KU-14
					ROD UPG		1038	1038		

SUB-AREA REPEAT FAILURE TOTALS
 COUNT CLE CM TOTAL
 ROD
 TBG 3 6441 342 6783
 NEXT FIN

SOUTHWESTERN PETROLEUM SHORT COURSE - 80

TABLE 3

EFSB23 - DETAIL/SUMMARY FOR EQUIPMENT BY DDAS

DIVISION: 6 MIDLAND

AREA: 2 MIDLAND

DISTRICT: 2 MIDLAND

SUB-AREA: 0

TITLE: 96241100 J.E. MABEE A NCT-1

DATE RANGE #1 010189 - 123189 #2 000000 - 000000 #3 000000 - 000000

R WELL DATE EQP SVC LOC CSE DEPTH COST COST TOTAL

REMARKS

C PNNNNCCSS

LABOR MATERLS
EQUIP

11	081889	ROD PO	CLP IMU	24	286	41	327	PONY ROD WAS PARTED; FISHED AND RETURNED TO PROD. (K.U. #4)
28	041089	ROD PO	CLP IMU	850	507	18	525	OLD HAMMER MARKS ON CPL. KU 41
63	073189	ROD PO	CLP IMU	200	477	18	495	(K.U. #16)
79	033189	ROD PO	CLP IMU	900	382	13	395	FISH & HANG ON KU 38
98	031889	ROD PO	CLP IMU ROD VIN	1500	1623 0	29 180	1652 180	STRIPPING JOB, REPLACED 6 RODS, KU 31
98	061589	ROD PO	CLP IMU	1400	382	39	421	FISH & HANG ON. KU 34
469	060589	ROD PO	CLP IMU	500	412	38	450	KU 34
534	050389	ROD PO	CLP IMU	50	380	18	398	CLP APPREARD TO BE RECONDITIONED W/OLD HAMMER MKS PD 156
546	050489	ROD PO	CLP IMU	300	382	18	400	KU 4

TABLE 4

DATE RUN 01/03/90

SUB-SURFACE EQUIPMENT FAILURE PROBLEM WELL DETAIL LISTING
REPORT NO 969012

PAGE 21


DISTRICT 2 MIDLAND				AREA 1 ODESSA		SUBAREA2 PENWELL			
PROPERTY NUMBER 96254307				PROPERTY NAME: PENWELL UNIT		RESERVOIR CODE:		WELL NUMBER 3313 00	
DATE	FAILURE DATA EQP SVC LOC CSE DEPTH			MAINT EQP TYP	COST LAB-EQP	COSTS MATRLS	TOTAL COST	REMARKS	
12/12/88	TBG PO	BDY WER	2790		3402	66	3468	TSTD TBG. SPLIT(WEAR W/MODERATE CORR)REP 35-3/4 CLP, RAN 4 NEW 1-1/2" K-BARS, NEW PMP & ANC. KU-3	
				TBG RMN		198	198		
				PMP RMN	35	1081	1116		
				ANC RMN	35	135	170		
				ROD UPG		1155	1155		
5/24/89	TBG PO	BDY WER	3500		2572	80	2652	RAN NEW STRNG OF 2-3/8 J55 TBG. RAN 11 RLR RDG, REP ALL CPLGS W/RODCOTE CPLGS(WR). REP PMP & ANC. KU14	
				TBG UPG	400	9720	10120		
				ROD UPG		2394	2394		
				PMP RMN	35	484	519		
				ANC RMN	35	232	267		
							22059		

YEAR ENDING: 6/30/89

WELLS WITH FAILURES EQUAL TO OR GREATER THAN:
2 - ROD; OR 2 - TBG; OR 2 - PMP; OR 2 - HPM; OR 2 - SPM; OR 4 - TOTAL

TABLE 5

ODESSA AREA Sub-Surface Failures



ODESSA AREA Sub-Surface Failures By Equipment Type





TABLE 6

ODESSA AREA Sub-Surface Failure Rate



ODESSA AREA Sub-Surface Failure Rate






TABLE 7

ODESSA AREA 2ND QTR 1989 TUBING FAILURES



LOCATION


ODESSA AREA 2ND QTR 1989 TUBING FAILURES



CAUSE


TABLE 8

ODESSA AREA 2ND QTR 1989 ROD FAILURES



LOCATION

ODESSA AREA 2ND QTR 1989 ROD FAILURES



CAUSE

TABLE 9

Chemical Treating Cost



TABLE 10

QUARTERLY SUB-SURFACE EQUIPMENT FAILURE SUMMARY

FAILURES

2ND QUARTER 1989 / 1ST QUARTER 1989

	NUMBER		FAILURE COST \$		\$ PER FAILURE	
Rods	27	/ 36	26635	/ 50739	986	/ 1409
Tubing	57	/ 53	136566	/ 130474	2396	/ 2462
Pump	73	/ 77	141571	/ 141255	1939	/ 1834
ESP	1	/ 2	4601	/ 18028	4601	/ 9014
Other	5	/ 3	15009	/ 4219	3002	/ 1406
Inj/SWD	0	/ 2	0	/ 5337	0	/ 2669
Total	163	/ 173	324382	/ 350052	1990	/ 2023
% Change	-6%		-7%		-2%	

ROUTINE MAINTENANCE

2ND QUARTER 1989 / 1ST QUARTER 1989

	NO.		FAILURE COST \$		\$ PER FAILURE	
Rods	21	/ 32	39082	/ 69820	1861	/ 2182
Tubing	41	/ 43	215949	/ 214784	5267	/ 4995
Pump	68	/ 77	38908	/ 58836	572	/ 764
ESP	0	/ 3	0	/ 10523	0	/ 3508
Other	59	/ 75	62582	/ 69901	1061	/ 932
Inj./SWD	0	/ 1	0	/ 960	0	/ 960
Total	189	/ 231	356521	/ 424824	1886	/ 1839
% Change	-18%		-16%		3%	

REPEAT FAILURES

2ND QUARTER 1989 / 1ST QUARTER 1989

	NUMBER		FAILURE COST \$		\$ PER FAILURE	
Rods	2	/ 5	1043	/ 7796	522	/ 1559
Tubing	3	/ 3	6783	/ 5442	2261	/ 1814
Pump	4	/ 8	7841	/ 14999	1960	/ 1875
ESP	0	/ 0	0	/ 0	0	/ 0
Other	0	/ 0	0	/ 0	0	/ 0
Inj/SWD	0	/ 0	0	/ 0	0	/ 0
Total	9	/ 16	15667	/ 28237	1741	/ 1765
% Change	-44%		-45%		-1%	

TABLE 11

ODESSA AREA
SUBAREA SUMMARY

SUBSURFACE FAILURES BY EQUIPMENT TYPE

2ND QUARTER 1989 / 1ST QUARTER 1989

SUBAREA	RODS		TUBING		PUMPS *		OTHER **		TOTAL	
Andector	7	/ 4	12	/ 4	11	/ 11	0	/ 0	30	/ 19
Concho	7	/ 6	8	/ 10	12	/ 13	1	/ 3	28	/ 32
Ft.Stktn	1	/ 2	5	/ 8	8	/ 8	0	/ 1	14	/ 19
Kermit	2	/ 5	2	/ 2	14	/ 14	0	/ 2	18	/ 23
Orla	6	/ 12	4	/ 6	10	/ 12	1	/ 0	21	/ 30
Penwell	4	/ 7	26	/ 23	18	/ 19	4	/ 1	52	/ 50
Total	27	/ 36	57	/ 53	73	/ 77	6	/ 7	163	/ 173
% Change	-25%		8%		-5%		-14%		-6%	

COST PER FAILURE

(Excluding Preventive Maintenance)

2ND QUARTER 1989 / 1ST QUARTER 1989

SUBAREA	RODS		TUBING		PUMPS *		OTHER **		TOTAL	
Andector	721	/ 2831	2275	/ 2265	2104	/ 1845	0	/ 0	5099	/ 6941
Concho	1054	/ 1017	2089	/ 2359	2138	/ 1781	2830	/ 6113	8111	/ 11269
Ft.Stktn	658	/ 589	2084	/ 2568	2403	/ 2137	0	/ 638	5145	/ 5932
Kermit	832	/ 661	2501	/ 3255	1317	/ 1375	0	/ 5401	4649	/ 10692
Orla	1088	/ 1693	3849	/ 3116	1981	/ 2195	1684	/ 0	8601	/ 7004
Penwell	1342	/ 1217	2375	/ 2264	1961	/ 1849	8099	/ 13642	13777	/ 18972
Average	986	/ 1409	2396	/ 2462	1939	/ 1834	3268	/ 3941	1990	/ 2023
% Change	-30%		-3%		6%		-17%		-2%	

Remarks: (See individual subarea pages)

* Rod Pumps

** Includes PM's, INJ, SWD

TABLE 12

CHEMICAL TREATING COST
ODESSA AREA
2ND QUARTER 1989

	2ND QUARTER 1989	1ST QUARTER 1989	4TH QUARTER 1988	3RD QUARTER 1988
TOTAL TREATED PRODUCTION				
Oil, Bbl	866,865	855,751	937,348	982,600
Water, Bbl	7,414,175	7,129,687	8,153,103	8,597,016
Fluid, Bbl	8,281,040	7,985,438	9,090,451	9,579,616
% Change in Total Fluid	4%	-12%	-5%	
Water/Oil Ratio	8.55	8.33	8.70	8.75
Gas Well Gas, MCF	5,352	6,145	5,061	7,206
TREATING COST *				
Oil Wells, \$	310,808	305,687	310,721	292,952
Gas Wells, \$	46,045	32,043	51,681	39,020
Total, \$	356,853	337,730	362,402	331,972
AVERAGE COST PER				
Bbl Oil, \$	0.359	0.357	0.331	0.298
Bbl Fluid, \$	0.038	0.038	0.034	0.031
MMCF, \$ (Gas wells only)	8.60	5.21	10.21	5.41
Month, \$	118,951	112,577	120,801	110,657

* Includes surface & sub-surface

TABLE 13

MIDLAND DIVISION
ODESSA AREA
PROBLEM WELL SUMMARY
2ND QUARTER 1989

PENWELL SUB-AREA

LEASE	PRODUCTION			PMP		PUMP		POC	PMP	TBG	ROD	SKR	SN	FLUID	(PREV 12 MOS./CURRENT QTR)					COST	QTRS	PROB	PROBLEMS AND RECOMMENDATIONS
	BOPD	BWPD	MCFD	100%	EFF	SPM	LOS	TIME	Y/N	SIZE	SIZE	DES	BAR	DEPTH	LEVEL	ROD	TBG	PMP	OTH	TOT			
*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****	*****
W. E. CONNELL NCT-1 WELL NO. 40	10	86	5.7	231	41	7.0	126	24	N	1.50	2.875	76	-	7970	-	0/0	0/0	2/1	0/0	2/1	1701	2	Pump Wear (10 month run).
W. E. CONNELL NCT-2 WELL NO. 162	45	68	7.9	136	83	7.0	128	20	N	1.25	2.875	86	-	9699	-	0/0	1/0	5/2	0/0	6/2	28637	4	Pump problems. Slowed unit down.
ECTOR FEE UNIT WELL NO. 4	17	221	31.0	408	58	9.6	119	24	N	1.75	2.875	86	16	6534	3969	4/1	0/0	4/0	0/0	8/1	16679	4	Pump wear. Slowed unit down. Excess rod load. Review for FG rods.
ECTOR FEE UNIT II WELL NO. 5	77	178	90.6			UNIDRAULIC			N					12000		0/0	0/0	0/0	3/1	3/1	19929	1	FES.
ECTOR FEE UNIT II WELL NO. 6	76	256	125.5			UNIDRAULIC			N					12018		0/0	0/0	0/0	2/1	2/1	10360	1	Corrosion. Review corrosion program.
ECTOR FEE UNIT II WELL NO. 9	34	161	77.7			UNIDRAULIC			N					12059		0/0	2/2	0/0	0/0	2/2	55442	1	Replaced tbg string.
PENWELL UNIT WELL NO. 1357	101	148	64.9	304	82	7.0	144	15.5	Y	2.00	2.875	87	10	3856	3856	0/0	3/2	2/0	1/0	6/2	35991	2	Wear. Ran additional K-bars. Replaced tbg string.
PENWELL UNIT WELL NO. 1362	24	174	21.9	181	110	7.4	144	15.5	Y	1.50	2.875	76	6	3862	3862	2/0	3/0	2/1	0/0	6/1	36352	4	PMP wear. Clean out w/bailer on next failure.
PENWELL UNIT WELL NO. 1364	63	14	49.6	87	88	7.5	144	7.4	Y	1.50	2.875	76	8	3831	3831	0/0	2/1	0/0	0/0	2/1	23160	1	Tbg wear. New tbg string. Slowed unit down.
PENWELL UNIT WELL NO. 1367	16	337	8.8	392	90	7.0	144	20	Y	2.00	2.875	87	6	3831	3831	0/0	3/1	0/0	0/0	3/1	31686	2	Tbg corrosion and wear. New tbg string.

TABLE 14

MIDLAND DIVISION GUIDELINES FOR
CHEMICAL PROPOSALS

- I. General Testing Considerations
 - A. Compatibility Test
 - B. Comparison Test
 - C. Timing
- II. Corrosion Inhibitors
 - A. Failure Analysis
 - B. Polymer Breakthrough Analysis (If Applicable)
 - C. Wheel Tests
 - D. Emulsion Tendency Tests
 - E. Supporting Operational Data
- III. Scale Inhibitors
- IV. Residence Time Distribution
- V. Demulsifiers
- VI. Water Clarifiers (Reverse Demulsifiers)
- VII. Biocides
 - A. Bacteria Counts
 - B. Time Kill Studies
- VIII. Parffin Chemicals
- IX. Scale Removal Chemicals
- X. Combination Products
- XI. System Monitoring

TABLE 15

Texaco Inc.
Monthly Chemical Usage Report
June 1989

Vendor - Any Chemical Company
Sales Engineer - Mr. Corrosion
Texaco Engineer - Mr. Engineer

Lease/Well Name	Chemical Name	Chemical Type	Chemical Cost (\$/gal)	\$Truck or Contin.	Treatment Freq. (stops/mo)	Chemical Usage (gal/mo)	Flush (Bbls)	Total Cost (\$/mo.)	Target ppm	Actual ppm	Production			Monthly Cost		Coupon MPY (Cur/Prev)	Iron Count	Last Failure (date/*)
											BOPD	BWPD	MCFPD	Per BO	Per BF			
ANYLEASE UNIT																		
Batt No 1	P900	PARAFFIN	\$8.79	CONT	5	25		\$219.75	60	22	200	700	400	\$0.04	\$0.01			
Batt No 2	D700	DEFOAM	\$8.25	AS NEEDED		30		\$247.50	60	2	1800	8600	2000	\$0.00	\$0.00			
	EM4000	EMULSION	\$11.84	CONT	18	121		\$1,432.64	60	9				\$0.03	\$0.00			
1287	COR1000	Corrosion	\$11.00	\$0.82	4	4	2	\$67.96	50	49	35	29	6	\$0.06	\$0.03			12-01-88*
	B3000	Biodisper	\$9.50			2			20	24								
1356	COR2000	Corrosion	\$9.00	\$0.82	4	12	2	\$167.92	50	53	39	137	22	\$0.14	\$0.03	6.7/8.2	10	11-28-88
	B3000	Biodisper	\$9.50			6			20	27								
1357	COR1000	Corrosion	\$11.00	CONT	2.49	18.675		\$224.66	60	59	101	148	6	\$0.07	\$0.03			10-9-88*
1358	COR2000	Corrosion	\$9.00	\$0.82	4	8	2	\$117.92	50	46	26	109	14	\$0.15	\$0.03			7-16-88
	P1100	Paraffin	\$6.00			4			20	23								
1362	COR1000	Corrosion	\$11.00	CONT	1.76	13.2		\$158.80	60	59	33	143	28	\$0.16	\$0.03	.90/.95		11-09-88
										0								
1363	COR2000	Corrosion	\$9.00	\$0.82	4	8	2	\$117.92	50	59	14	92	143	\$0.28	\$0.04		5	9-22-88
	P1100	Paraffin	\$6.00			4			20	30								
1364	COR1000	Corrosion	\$11.00	\$0.82	4	4	2	\$67.96	50	40	72	7	11	\$0.03	\$0.03	10.36/12.0		3-3-89
	B3000	Biodisper	\$9.50			2			20	20								
1365	SI																	

* Indicates A Corrosion Related Failure

TABLE 16

EFS - EQUIPMENT EVALUATION

Installation Type Roller Rod Guides Installation Date 4/89

Reason for Installation Reduce Rod/Tbg Wear

Installed Where Test Lease Well No. 3

Supplier Name/Contact XYZ Corp./Mr. Salesman Phone No. 987-6543

Approximate Equipment Cost 7/8" x 2 7/8" \$175

Texaco Contact Mr. Foreman Phone No. 123-4567

1) Quarterly Performance Comments: There were 6 roller rod guides installed in Well No. 3 due to excessive Rod/Tbg wear. There has not been a failure for 2 months.

2) Quarterly Performance Comments: Well No. 3 has gone 5 months without a Rod/Tbg failure. Prior to installing the roller rod guides the well had a Rod/Tbg failure every 45 days.

3) Quarterly Performance Comments: Well No. 3 had a pump failure 7 months after the roller rod guides were installed. The rods and tubing were inspected and showed no signs of wear, however, the wheels on the guides were worn and new wheel kits were installed.

4) Quarterly Performance Comments: _____

TABLE 17